

# ROUSH<sup>®</sup> PERFORMANCE

## VOLUNTARY SAFETY RECALL NOTICE

ROUSH Performance Products (“ROUSH”) has determined that a defect which relates to motor vehicle safety exists in ROUSH branded front struts sold in the aftermarket for installation on Model Year 2005, 2006, and 2007 Ford Mustang GT vehicles. ROUSH is conducting a voluntary recall program to replace these parts at no charge.

### Items Covered by this Recall

The aftermarket ROUSH products covered by this recall are:

(a) **ROUSH branded front struts as a stand alone component.**

The struts are marked as Part # **R06020048-13-AA** or **R06020048-13-AB**.

They are sold under Retail Part # **401297**, with Shipping Label #**R06020064-13-AA**.

(b) **ROUSH branded front struts as a suspension kit.**

The struts in the kit are marked as Part # **R06020048-13-AA** or **R06020048-13-AB**.

They are sold under Retail Part # **401296**, with Shipping Label #**R06000019-13-AAR**.

### Why We Are Taking This Action

ROUSH has determined that the front anti-roll bar attachment bracket on the front strut can separate from the strut housing due to inconsistent welding. This could result in a clunking noise and or poor handling in extreme or emergency maneuvers. Possible tire side wall damage may occur if the broken bracket contacts the tire, which may increase the risk of a crash.

### What We Will Do

ROUSH is offering to provide, at no charge, replacement front struts to owners of the covered ROUSH branded front struts.

### What You Should Do

If you have the ROUSH branded front struts covered by this notification, the product is covered by this recall and you should call ROUSH at (866)-307-6788 to receive a replacement free of charge.

If you previously paid to replace the ROUSH branded front struts that failed due to this defect, ROUSH will reimburse you for your costs according to the **STRUT RECALL PRE-NOTIFICATION REIMBURSEMENT PROGRAM**. To be eligible for reimbursement, you will be required to complete a form, which you can obtain by calling ROUSH at (866)-307-6788 or by downloading it from our website at:

**[http://www.ROUSHperformance.com/recall\\_struts.shtml](http://www.ROUSHperformance.com/recall_struts.shtml)**. To obtain the reimbursement, you must submit this form with the required documentation to ROUSH.

If you no longer own the vehicle in which you installed the ROUSH branded front struts covered by this recall, please call us at (866)-307-6788 and provide us with the vehicle identification number (VIN) of the vehicle and the name and address of the current owner (if you know them) so we may contact him or her about this recall.

We regret any inconvenience that this recall may cause you, but we want to assure that any possible safety problems in our products are remedied promptly.

Sincerely,

**ROUSH PERFORMANCE PRODUCTS, INC.**